



Mantle Burn-in Process

Please read these instructions before use

This process may produce excessive smoking and discoloration of the mantles glass fiber bowl due to leftover oils from manufacturing.

1. Plug in unit in a very well ventilated area.
2. Plug in the black jumper into the probe port
3. Turn on the mantle
4. Set the temperature to 40°C
5. Once the temperature reaches the set point, increase the setting by 5°C.
(Repeat this process until 300°C is reached.)
6. Turn off the mantle and let it cool to room temperature.